CARR - 438

1811 STONE CHAPEL ROAD

late 19th century

Warfieldsburg

private

1811 Stone Chapel Road is a late nineteenth century house typical of medium-scale architecture constructed in the region's small towns and villages. It is a two-story structure with a four bay facade. It contains two doors-one on each of the central bay--an unusual feature found frequently in German settled areas of southern Pennsylvania and central Maryland.



DEPARTMENT OF PLANNING AND DEVELOPMENT

225. N. Center Street Westminster, Maryland 21157

WESTMINSTER PLANNING DISTRICT

FIELD SHEET--HISTORIC RESOURCES SURVEY

SUFVEY NUMBER:	ARR - 438
NEGATIVE FILE NUM	MBER:
UTM REFERENCES:	
UTM REFERENCES: Zone/Easting/N	Vorthing

U.S.G.S.	QUAD.	MAP:	New	Undson


PRESENT FORMAL NAME:

	TRESENT FORMAL NAME:
COUNTY: CARROLL	ORIGINAL FORMAL NAME:
TOWN: Warfields burg	
LOCATION: 1811 Stone Chape Road	PRESENT USE: 100 durce
The state of the s	ORIGINAL USE: 428 dence
TAX MAP 51 Block 16 P-92	ARCHITECT/ENGINEER:
COMMON NAME:	
7 1	BUILDER/CONTRACTOR:
FUNCTIONAL TYPE: Residence	Divide
OWNER: Donald S. Shipley ADDRESS: 1811 Stone Chapel Road	PHYSICAL CONDITION OF STRUCTURE:
ADDRESS: 1811 STAR Charle TROOM	Excellent () Good (×) Fair () Poor ()
ACCESCIPILITY TO DIST	
ACCESSIBILITY TO PUBLIC:	THEME:
Yes () No () Restricted () LEVEL OF SIGNIFICANCE:	STYLE:
Local () State () National ()	DATE BUILT: late 19th century
GENERAL DESCRIPTION:	
Structural System	
1. Foundation: Stone (X) Brick () Concrete (() Congrete Block ()
- "dir princinte	
A. Wood: Log () Post and Beam () Balloo	on (X)
b. wood Bearing Masonry: Brick () Stone () Concrete () Concrete Block ()
3. Wall Covering: Weatherboard (X) German Sidi	ng () Board and Batten ()
wood Sningle () Shiplap ()	Novelty () Stude () Chart Marial ()
	() Brick Veneer () Stone Veneer ()
DOMUTIE LALLEIN:	Other:
4. Roof Structure	
A. Truss: Wood (X) Iron () Steel () Co B. Other:	ncrete ()
5. Roof Covering: Slate () Wood Shingle ()	Asphalt Shingle () Sheet Metal (×)
Built Up () Rolled () Til	e () Other:
7. Other:	
Appendages: Porches () Towers () Cupolas ()	Down () at t
DITTO X / WILLS / I (ILUQI)	
Roof Style: Gable (x) Hip () Shed () Flat ()	Managard () Comband () The same
Saw Tooth () With Monitor () With I	Relicast () With Demont ()
"ILLI TAISE FFORE () () Ther!	belieast () with Parapet ()
Number of Stories: 2	
Number of Bays: 4 y	Entrance Location: 2 entrances - central bays
Approximate Dimensions:	and the same
-dREAT TO STRUCTURE.	LOCAL ATTITUDES

1	-AREAT TO STRUCTURE:	
I	No Threat (x) Zoning () Roads ()
ı	Development () Deterioration ()	_
l	Alteration () Other:	

LOCAL ATTITUDES:
Positive (*) Negative ()
Mixed () Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESC	
two entrances in untral bodys as found or	some houses in this region
untral stone flue change	Dentify and the land of the la
	STATES SERVICE SELECTION
THE COLUMN NAME OF THE PARTY.	THE RESERVE AND THE PARTY AND LOSS.
THUR DOOR - CESSION	
Salar cases legislated	J15263 United
	The state of the s
RELATED STRUCTURES: (Describe)	
CENTRAL WAY THE ATTEMPT	and all the second second
Transmire to soft june Juliani	Land of the second of the second
	SALARY AS NO CHILITOSID
STATEMENT OF SIGNIFICANCE:	LAND TO THE PARTY OF THE PARTY
() dools served () served ():	The same of the sa
1862 Martenet's Map:	man for the second of the seco
1877 LG & S Atlas: H. Gv.slow	
- commission of the same of the same of	
milel a service requestion	
SURROUNDING ENVIRONMENT: Open Lane ()Woodland ()Scattered Buildin Moderately Built Up ()Densely-Built Up () Residential () Commercial () Agricultural () Industrial () Roadside Strip Development ()	ORGANIZATION:
Other:	DATE RECORDED:





- 1. CARR-438 1811 STONE CHAPEL ROAD
- 2. Carroll County, Maryland3. Joe Getty
- 4. August 1983
- 5. Md. Historical Trust, Annapolis, Md.
- 6. South elevation (camera facing north)
- 7. 1/1